THERMOLEC

Split steam Error Code 5

CAUTION

WARNING For electric shock
Disconnect all power before working within the unit

Must be performed by licensed technician