


THERMOLEC

D46 Flowchart



NOTE: Please put back connections and jumpers as per wiring diagram