


D21-TS Flowchart

CAUTION

WARNING For electric shock
Disconnect all power before
working within the unit

Must be performed by
licensed technician



NOTE: Please put back connections and jumpers as per wiring diagram