


**THERMOLEC**  
D21-PS Flowchart

**CAUTION**  
WARNING For electric shock  
Disconnect all power before  
working within the unit  
  
Must be performed by  
licensed technician



**NOTE: Please put back connections and jumpers as per wiring diagram**